

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

Jan 2/4/03
RECEIVED
JAN 17 2003

ANNUAL REPORT OF MINING OPERATIONS

DIV. OF OIL, GAS & MINING

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-2002 To (mo./yr.) 1-2003
2. DOGM File Number (Mine No.) 51700146
3. Mine Name: Milla' MARTINIQUE
4. Mineral(s) Mined (or permitted to mine): GOLD - Precious metals
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, ____ 1/4, SW 1/4, Section 25, Township 31 S, Range 11 E.
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: MARTINIQUE Mining Corp.
8. Permanent Street Address: 1215 BUSH ST. P.O. Box 1688
City, State, Zip: CARLIN NEVADA 89822
Phone: 775-754-2188 Fax: SAME
9. Company Representative (or designated operator):
Name: Kim E. Wilson
Title: -
Business Address: -
City, State, Zip: -
Phone: - Fax: -
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 25 tons

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Ore sampling - stockpiles taken -
Equipment tear down and stockpile
Removal.

5. How much additional acreage was disturbed during the past year? -0-

6. How much acreage was reclaimed during the past year? 1 acre

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

We are currently reclaiming this site -
Earth work is 90% complete - area out side
our perimeter is seeded and smoothed
Equipment is ready for transport.

8. What is the total disturbed acreage of entire project at years end? 1/4 acre

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

We will complete the removal of equipments
this season and the site will be completely
reclaimed and repaired.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Kim E. Wilson

Title of Operator:

President

Signature of Operator:

Kim E. Wilson

Date:

1-15-03

WIRE GOLD FROM
THE BROMIDE BASIN
MINES.

